

Significant Digits

Regardless of how precise the measuring instrument, no measurement is exact and always involves a guess.

When recording a measurement you should usually try to read 1 digit past the least count digit.

You have to make a guess as to what the last digit is that you record. → this last digit is called the uncertain digit because you have made a guess

A significant digit (figure) is one that has been measured with certainty or properly estimated.

Consider a 30 cm with mm markings and you record the measurement to be:

15.278592785192 cm ← impossible to write this if using mm as your least count

↑ need to guess about this digit.

A better measurement to record would be:

15.28 cm

15.27 cm → 4sf
certain uncertain

* When counting significant digits in a measurement, you count all the certain digits and the ONE uncertain digit.

Examples

$$\underline{203.4} \text{ cm} \rightarrow 4 \text{ sd} \quad (\text{LC} = 1 \text{ cm})$$

certain digits
uncertain digit

$$\underline{4.07} \text{ cm} \rightarrow 3 \text{ sd} \quad (\text{LC} = 1 \text{ mm or } 0.1 \text{ cm})$$

certain digits
uncertain digit

What about those zeroes?

$$\underline{14.002} \text{ cm} \rightarrow 5 \text{ sd}$$

$$\underline{60.2} \text{ cm} \rightarrow 3 \text{ sd}$$

A zero is always significant if it is between two non-zero digits.

$$\underline{29.20} \text{ cm} \rightarrow 4 \text{ sd}$$

$$\underline{7.020} \text{ cm} \rightarrow 4 \text{ sd}$$

A zero is significant if it is to the right of the decimal and after a non-zero digit.

$$\underline{0.08517} \text{ cm}$$

leading zeroes
are not significant
 $\Rightarrow 8.517 \times 10^{-3} \text{ cm}$

Leading zeroes are never significant.

$$25000 \text{ m}$$

↑ The problem with writing a measurement like this is that we do not know how precise the measuring instrument is.
If we don't know how precise, then we take the least precise value.
(LC = 10,000 m or 1000 m or 100 m or 10 m)

25 ₀₀₀ m → place values How do you know what THE LEAST COUNT IS?

Certain digit
uncertain digit
2sd

$$\begin{aligned} \text{Some older textbooks use: } & 25000. \text{ m } (5 \text{ sd}) \\ & 2500\bar{0} \text{ m } (5 \text{ sd}) \end{aligned}$$

A better way to show significant digits:

$$\underline{2.5} \times 10^4 \text{ m} \rightarrow 2 \text{ sd} \quad (\text{LC} = 10,000 \text{ m})$$

certain uncertain

$$\underline{2.50} \times 10^4 \text{ m} \rightarrow 3 \text{ sd} \quad (\text{LC} = 1000 \text{ m})$$

certain uncertain digit

$$\underline{2.500} \times 10^4 \text{ m} \rightarrow 4 \text{ sd} \quad (\text{LC} = 100 \text{ m})$$

$$\underline{2.5000} \times 10^4 \text{ m} \rightarrow 5 \text{ sd} \quad (\text{LC} = 10 \text{ m})$$

Trailing zeroes are not significant (unless you know more about the precision of the measuring instrument).

What about $370.00 \text{ mm} \rightarrow 5 \text{ sd}$.

There are some things we don't need to worry about for significant digits... they are exact numbers.

- counting numbers (52 pennies)
- conversions... $1 \text{ m} = 100 \text{ cm}$
 $1 \text{ ft} = 12 \text{ in}$
- numbers in formulas:

$$A = \frac{1}{2}bh$$

Rules For Significant Digits

Digits from 1-9 are always significant.

Zeros between two other significant digits are always significant

- One or more additional zeros to the right of both the decimal place and another significant digit are significant.

Zeros used solely for spacing the decimal point (placeholders) are not significant.